












# Cover Rx assembly instructions

First inspect the included (2) hardware bags and all other parts (see figure 1) to make sure there is nothing missing

## HARDWARE AND PARTS LIST:

- A  (2) of each - *attaches main body to pivot arm tabs*
- B    (2) total (*B and C are identical*) - *connects to air shock*  
 C   (*B is Pre-installed*)
- D  (2) Pins
- E   (4) Screws + (2) Nuts - *attaches baseplate to support legs*
- F   (2) of each - *attaches main body to support legs*

G - (1) Gas Shock

H - (1) Base Plate

I - (2) Support Legs

J - (1) Pivot Arm

K - (1) Main Body

L - (2) Short U-Arm Elbows

M - (2) Long U-Arm Elbows

N - (2) U-Arm Spacers

P - (2) Bumper Knobs

Also includes all tools needed  
box wrench and allen wrench

